# BELL SYSTEM PRACTICES AT&TCo Standard

# REPLACING PAGE ADDENDUM Filing Instructions:

1. REMOVE FROM THE SECTION THE PAGES NUMBERED THE SAME AS THOSE ATTACHED TO THIS PINK SHEET.

2. INSERT THE ATTACHED PAGES INTO THE SECTION IN THEIR PLACE.

.....

3. PLACE THIS PINK SHEET AHEAD OF PAGE 1 OF THE SECTION.

ADDENDUM 463-311-105 Issue 1, April 1974

# VOICE CONNECTING ARRANGEMENT LVH 109A AND 110A INTERCONNECTING UNIT 69H APPARATUS MOUNTING 606A PANEL

### 1. GENERAL

1.001 This addendum supplements Section 463-311-105, Issue 3. The attached pages must be inserted in the section in accordance with the filing instructions above.

1.002 This addendum is issued to change the maintenance tests to use 1000-Hz test tone instead of dial tone.

### Attached:

Page 7 dated April 1974—revised Page 8 dated April 1974—reissued

## 5. MAINTENANCE

The following change applies to Part 5 of the section:

(a) 5.02—revised